

How to Install Web Manager for Matrix-504

- Step 1 Download the compressed installation file: *arwebmgr.tar* from Artila web download page
- **Step 2** Use ftp to upload this tar file to Matrix-504
- Step 3 Decompress this tar file by issue command tar xvf arwebmgr.tar –C /
- Step 4 Reboot Matrix-504
- Step 5 Use browser to visit Matrix-504 IP and port number 8080 as followed

Login to Matrix 504		
Y	You must enter a username and password to login to the Matrix 504.	
Username	root	
Password		

- **Step 6** Login with password (root/root or guest/guest)
- Step 7 Once you see this page, you are ready to use Web Manager

	and the second	
		\ <u>System Manager</u> > <u>System Information</u> >
User Manager	N	
Uter List System Manager	Matrix504	
Network Interfaces	Time on system Mon Oct 27 14:46:16 UTC 2014	
DNS	Firmware Linux 2.6.29.4 Loader 2.0.13-64M	
System Time Login Message	Kernel build #1 PREEMPT Fri Oct 17 10	
Bootup &	Filesystem build #202 PREEMPT Mon Aug 27 11	
Shutdown Running Process	Processor information ARM926EJ-S rev 5 (v51) System untime 5 min	
Disk Manager	Running processes <u>38</u>	
System Information	CPU load averages 0.00(1 min) 0.00(5 min) 0.00(15 min)	
Software	CPU usage 0.9% user, 1.6% kernel, 0.0% IO, 97.4% idle	
Manager Software list	200 MB used 244 MB total	
Software search	Local disk space 200 MB dsed, 200 MB total	
Server	Package updates 141 packages installed	
Artila Utility		
Firmware Update		
Uart Setting		
GPIO Setting		
Other		
Logout		